

A sturdy nylon gear loop with a velcro break away attachment point designed to hold connectors on Y lanyards when not in use.

Can be attached to the webbing straps of any fall arrest harness.


Maximum load: 5 kg.



Installation on the harness



Use as lanyard's connector loop



Ref.	Product name	Weight		Working load max
		g	oz	kg
0940	GEAR LOOP	6	0.2	5